

LTPP SPS Project Deviation Report Project Summary Sheet		State Code Project Code	<u>0 6</u> <u>0 8 0 0</u>
Project Classification Information			
SPS Experiment Number: 8		State or Province: California	
LTPP Region:		<input type="checkbox"/> North Atlantic <input type="checkbox"/> North Central <input type="checkbox"/> Southern <input checked="" type="checkbox"/> Western	
Climate Zone:		<input type="checkbox"/> Dry-Freeze <input checked="" type="checkbox"/> Dry-No Freeze <input type="checkbox"/> Wet-Freeze <input type="checkbox"/> Wet-No Freeze	
Subgrade Classification:		<input checked="" type="checkbox"/> Fine Grain <input type="checkbox"/> Coarse Grain <input type="checkbox"/> Active (SPS-8 Only)	
Project Experiment Classification Designation (SPS 1, 2 and 8):		8	
Construction Start Date: May 1999		Construction End Date: July 1999	
Deviation Summary			
Site Location Deviations:		<input type="checkbox"/> No Deviations <input checked="" type="checkbox"/> Minor Deviations <input type="checkbox"/> Significant Deviations	
Construction Deviations:		<input type="checkbox"/> No Deviations <input checked="" type="checkbox"/> Minor Deviations <input type="checkbox"/> Significant Deviations	
Data Collection and Processing Status Summary			
Inventory Data (SPS 5,6,7,9):		<input type="checkbox"/> Complete Submission <input type="checkbox"/> Incomplete <input type="checkbox"/> Data Not Available <input checked="" type="checkbox"/> N/A	
Materials Data:		<input checked="" type="checkbox"/> All Scheduled Samples Obtained and Tested <input type="checkbox"/> Incomplete/No Test Data	
Construction Data:		<input type="checkbox"/> All Required Data Obtained <input type="checkbox"/> Incomplete/Missing Data Elements	
Historical Traffic Data:		<input type="checkbox"/> All Required Historical Estimates Submitted (SPS 5,6,7,9) <input type="checkbox"/> Required Estimates Not Submitted <input checked="" type="checkbox"/> N/A	
Traffic Monitoring Equipment:		<input type="checkbox"/> WIM Installed On-Site <input type="checkbox"/> AVC Installed On-Site <input type="checkbox"/> ATR Installed On-Site <input checked="" type="checkbox"/> No Equipment Installed	
Traffic Monitoring:		<input type="checkbox"/> Preferred <input type="checkbox"/> Continuous <input type="checkbox"/> Minimum <input type="checkbox"/> Below Minimum <input checked="" type="checkbox"/> Site Related	
Traffic Monitoring Data:		<input type="checkbox"/> Monitoring Data Submitted <input type="checkbox"/> No Monitoring Data Submitted	
FWD Measurements:		<input type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Construction Tests Performed <input checked="" type="checkbox"/> Post-Construction Tests Performed	
Profile Measurements:		<input type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Post-Construction Tests Performed	
Distress Measurements:		<input type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Post-Construction Tests Performed	
Maint. & Rehab. Data:		<input type="checkbox"/> Complete Submission <input type="checkbox"/> Incomplete <input type="checkbox"/> Data Not Available <input checked="" type="checkbox"/> N/A	
Report Status			
Materials Sampling and Test Plan:		<input type="checkbox"/> Document Prepared <input checked="" type="checkbox"/> Final Submitted to FHWA	
Construction Report:		<input type="checkbox"/> Document Prepared <input type="checkbox"/> Final Submitted to FHWA	
AWS (SPS 1,2,&8):		<input type="checkbox"/> AWS Installed <input checked="" type="checkbox"/> AWS Installation Report Submitted to FHWA <input type="checkbox"/> N/A	

LTPP SPS Project Deviation Report Project Summary Sheet		State Code <u>06</u> Project Code <u>0800</u>	
Project Classification Information			
SPS Experiment Number: <u>8</u>		State or Province: <u>California</u>	
LTPP Region:		<input type="checkbox"/> North Atlantic <input type="checkbox"/> North Central <input type="checkbox"/> Southern <input checked="" type="checkbox"/> Western	
Climate Zone:		<input type="checkbox"/> Dry-Freeze <input checked="" type="checkbox"/> Dry-No Freeze <input type="checkbox"/> Wet-Freeze <input type="checkbox"/> Wet-No Freeze	
Subgrade Classification:		<input checked="" type="checkbox"/> Fine Grain <input type="checkbox"/> Coarse Grain <input type="checkbox"/> Active (SPS-8 Only)	
Project Experiment Classification Designation (SPS 1, 2 and 8):		<u>8</u>	
Construction Start Date: <u>May 1999</u>		Construction End Date: <u>July 1999</u>	
Deviation Summary			
Site Location Deviations:		<input type="checkbox"/> No Deviations <input checked="" type="checkbox"/> Minor Deviations <input type="checkbox"/> Significant Deviations	
Construction Deviations:		<input type="checkbox"/> No Deviations <input checked="" type="checkbox"/> Minor Deviations <input type="checkbox"/> Significant Deviations	
Data Collection and Processing Status Summary			
Inventory Data (SPS 5,6,7,9):		<input type="checkbox"/> Complete Submission <input type="checkbox"/> Incomplete <input type="checkbox"/> Data Not Available <input checked="" type="checkbox"/> N/A	
Materials Data:		<input checked="" type="checkbox"/> All Scheduled Samples Obtained and Tested <input type="checkbox"/> Incomplete/No Test Data	
Construction Data:		<input type="checkbox"/> All Required Data Obtained <input type="checkbox"/> Incomplete/Missing Data Elements	
Historical Traffic Data:		<input type="checkbox"/> All Required Historical Estimates Submitted (SPS 5,6,7,9) <input type="checkbox"/> Required Estimates Not Submitted <input checked="" type="checkbox"/> N/A	
Traffic Monitoring Equipment:		<input type="checkbox"/> WIM Installed On-Site <input type="checkbox"/> AVC Installed On-Site <input type="checkbox"/> ATR Installed On-Site <input checked="" type="checkbox"/> No Equipment Installed	
Traffic Monitoring:		<input type="checkbox"/> Preferred <input type="checkbox"/> Continuous <input type="checkbox"/> Minimum <input type="checkbox"/> Below Minimum <input checked="" type="checkbox"/> Site Related	
Traffic Monitoring Data:		<input type="checkbox"/> Monitoring Data Submitted <input type="checkbox"/> No Monitoring Data Submitted	
FWD Measurements:		<input type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Construction Tests Performed <input checked="" type="checkbox"/> Post-Construction Tests Performed	
Profile Measurements:		<input type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Post-Construction Tests Performed	
Distress Measurements:		<input type="checkbox"/> Preconstruction Tests Performed <input checked="" type="checkbox"/> Post-Construction Tests Performed	
Maint. & Rehab. Data:		<input type="checkbox"/> Complete Submission <input type="checkbox"/> Incomplete <input type="checkbox"/> Data Not Available <input checked="" type="checkbox"/> N/A	
Report Status			
Materials Sampling and Test Plan:		<input checked="" type="checkbox"/> Document Prepared <input checked="" type="checkbox"/> Final Submitted to FHWA	
Construction Report:		<input type="checkbox"/> Document Prepared <input type="checkbox"/> Final Submitted to FHWA	
AWS (SPS 1,2,&8):		<input type="checkbox"/> AWS Installed <input checked="" type="checkbox"/> AWS Installation Report Submitted to FHWA <input type="checkbox"/> N/A	

LTPP SPS Project Deviation Report Site Location Guidelines Deviations	State Code	<u>0</u> <u>6</u>
	Project Code	<u>0</u> <u>8</u> <u>0</u> <u>0</u>

- ☒ Comments Pertain to All Test Sections on Project
☐ Comments Pertain Only to Section(s): (Specify) _____

Site Location Guidelines Deviation Comments:

- All sections - The test sections are located on gently curving alignment.

LTPP SPS Project Deviation Report Construction Guidelines Deviations	State Code <u>0 6</u> Project Code <u>0 8 0 0</u>
<input checked="" type="checkbox"/> Comments Pertain to All Test Sections on Project <input checked="" type="checkbox"/> Comments Pertain Only to Section(s): (Specify) <u>060811, 060812</u>	
Construction Guidelines Deviation Comments: <u>Paving was stopped for more than 1 hour on both sections</u> <ul style="list-style-type: none"> • Section 060811 - A dowel basket was hooked by the longitudinal tie bar inserter at section station 0+59.0. The dowel basket was bent out of shape. The dowel basket was dug out and replaced with a different dowel basket. The concrete in this area was not compacted mechanically. This caused paving work stoppage of more than 1 hour. • Section 060812 - Small piles of concrete were left silting on grade between section stations 0+70 x 0+80 for more than 1 hour. 	

